

FITNESS CERTIFICATE

To be filled by the Inspecting officer (Assistant Engineer)
(Re: G.O Ms.20/70/PWD Dt. 23/01/1970)

ANNEXURE B

- | | | |
|---|--|--|
| | Name of School | : BPM MODEL SCHOOL |
| 1 | Name of officer | : NITHYA KURUP |
| 2 | Location | : PERETIL, ATTINGAL |
| 3 | Period for which the certificate is issued | : 2026-27 |
| 4 | Types of Building | : PERMANANT RCC BUILDING |
| | | (TWO STORIED) - 2 X 10.3 X 7.85X3.6 |
| | | (TWO STORIED) - 2X20X7.85X3.6 |
| | | (THREE STORIED) - 3X32.5X9.5X3.6 |
| | | (THREE STORIED) - 3X12.3X8.9X3.6 |
| 5 | Nature of defect if any | : NIL |
| | a) Foundation and basement | : |
| | b) Superstructure | : |
| | c) Doors and Windows | : |
| | d) Wood work wrought and put up | : |
| | e) Roof | : |
| | f) Flooring | : |
| | g) Miscellaneous (cracks if any) | : |
| 6 | Any Major defects notices which will render the building unsafe in any | : NIL |
| 7 | Whether maintainance works have been done properly | : YES |
| 8 | Whether the structure is sound or not for conducting classes | : YES, The structure is sound for conducting classes under normal wind and weather conditions. |

Note:-

- 1 *Stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc*
- 2 *Any additional observations if deemed necessary for the certificate may be furnished separately with the certificate*
- 3 *The School premisis should be cleaned periodically, bushes should be cleared and it should be ensure that there is no presence of reptiles or harmfull creatures*
- 4 *Verification of Annexure A and fitness certificate is issued based on the examination conducted on the date of inspection, Item no.9 in Annexure A, that the electrical wiring in the school building shall examined by an approved/Licensed Wireman, A certificate stating that the wiring of the school building is safe must be obtained from the wireman who inspected the wiring within one month and a copy must be submitted to the this office too.*

CERTIFICATE

Certified that the school was inspected by me on 16/07/2026 and found to be fit to conduct classes for the period for 2026-2027 Academic year under normal weather conditions for the reason stated above. This certificate is only for the structural safety related to civil constructions. Separate certificates for the fire safety and safety of electrical installation, electrical lines, conduits shall be obtained from the concerned departments.

Place : *Othoor*
Date : *16/07/2026*



Assistant Engineer

[Signature]
ASSISTANT ENGINEER
Local Self Government Department
Othoor Grama Panchayat